



Product Change Notification

TE Connectivity

Product Change Notification: P-19-016786

PCN Date: 15-JAN-19

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Tubing products impacted by new Prop 65

Description of Changes

This PCN is to inform our customers of additional labelling on some Tubing products. The requirements of the Proposition 65 (Prop 65) a Californian Safe water and Toxic Enforcement Act of 1986 now requires that we warn customers that some of our tubing products contain Antimony in the material make up. This requirement only applies to customer in California. However, as TE cannot predict which products will arrive with customers in California we have to label all Antimony containing products, of course these products will be delivered also to customers outside of California. No Action needs to be taken by our customers outside of California unless the products you receive are directly being forwarded through the supply chain to further customer in California USA in which case the warning must accompany the product. Please share this information with your colleagues so they will also be informed.

Reason for Changes:

Product improvement.To comply with Californian Prop 65 regulations.

Estimated Dates:

Last Order Date (Obsolete Parts Only): **First Date To Ship** (Changed Parts Only):

16-JAN-2019

Last Ship Date (Obsolete Parts Only): **Last Date for Mixed Shipments:** (Changed Parts Only):

No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0021032009	NO			"9-1190015-4", "RBK-ILS-125-NR3-0-STK"			
0146662002	NO			"2-1198052-6", "DSPL-NR3-0-STK"			
142003-000	NO			"1-1191029-3", "RNF-100-3/4-BK-FSP"			
1550634001	NO			"6-1191120-8", "VERSAFIT-3/8-0-FSP"			
1880984007	NO			"2-1191365-4", "RAYRIM-NR7-0-SP"			
2029154002	NO			"1-1191471-8", "RNF-150-1/2-0-SP"			
2031134002	NO			"5-1191472-5", "VERSAFIT-3X-1/2-0-SP"			
2056350005	NO			"3-1191490-3", "ES-CAP-NO.3-B8-0-40MM"			
2056350007	NO			"3-1191490-4", "ES-CAP-NO.3-B8-0-50MM"			
206247P038	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			
2376334004	NO			"1191747-3", "RNF-3000-9/3-8-SP"			
3128592004	NO			"6-1192366-6", "CGAT-12/4-0-STK"			
344153-000	NO			"1192592-8", "V4-3/16-0-SP"			
349871J001	NO			"2-1192632-5", "V4-7.0-0-SP-SM"			
3813914003	NO			"2-1192851-4", "VERSAFIT-3/64-0-SP"			
4051444001	NO			"6-1193057-8", "VERSAFIT-1/4-2-SP"			
415877P006	NO			"5-1193134-9", "FL2500-NO.1-I8-0-27MM"			
5020192003	NO			"9-1193753-3", "RP-4800-NO.6-0-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5020194004	NO			"9-1193753-5", "RP-4800-NO.6-0-SP"			
5038114002	NO			"7-1193792-6", "DCPT-12/6-45-SP"			
5038184001	NO			"1-1193793-1", "DCPT-26/13-45-SP"			
5038604008	NO			"1193794-5", "DCPT-6/3-45-SP"			
5039582014	NO			"8-1193803-1", "TPEM-NR8-0-STK"			
5050964002	NO			"9-1193817-4", "RNF-100-NO.301-BK-SP"			
5052842057	NO			"3-1193821-9", "RNF-100-3/64-BK-STK"			
5052984035	NO			"6-1193831-8", "RNF-100-3/32-9-SP", "RNF-100-3/32-9-SP"			
5052984151	NO			"6-1193831-9", "RNF-100-3/32-WH-SP"			
5053034048	NO			"5-1193837-1", "RNF-100-1/8-9-SP"			
5053034137	NO			"5-1193837-2", "RNF-100-1/8-WH-SP"			
5053074017	NO			"2-1193843-7", "RNF-100-3/16-6-SP", "RNF-100-3/16-6-SP"			
5053094268	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
5053194052	NO			"2-1193862-7", "RNF-100-1/2-0-SP"			
5053204012	NO			"3-1193865-7", "RNF-100-1/2-2-SP"			
5053292160	NO			"3-1193876-7", "RNF-100-1-BK-STK"			
5053302039	NO			"1193878-3", "RNF-100-1-RD-STK"			
5053394065	NO			"8-1193885-6", "RNF-100-2-BK-SP"			
5058714003	NO			"3-1193906-7", "VERSAFIT-1/8-9-SP"			
505872J005	NO			"7-1193906-2", "VERSAFIT-3/16-0-SP-SM"			
5069794007	NO			"4-1193947-1", "CGPT-1.2/0.6-0-SP"			
5069864018	NO			"1193953-5", "CGPT-12.7/6.4-0-SP"			
5069964007	NO			"8-1193957-7", "CGPT-6.4/3.2-9-SP"			
5142422002	NO			"6-1198047-0", "DSPL-NR4-0-STK"			
5338834002	NO			"3-1194191-1", "VERSAFIT-3X-1/8-0-SP"			
5500982001	NO			"3-1194338-9", "TAT-125-3/16-0-STK"			
5509094059	NO			"6-1194348-3", "ATUM-6/2-0-SP"			
5509124055	NO			"1194353-1", "ATUM-40/13-0-SP"			
5562734018	NO			"2-1194388-0", "VERSAFIT-1/16-0-SP"			
5575754001	NO			"9-1194397-4", "CGPT-18/6-0-SP"			
5677594005	NO			"2-1194496-8", "RNF-3000-12/4-0-SP"			
5677604005	NO			"2-1194497-8", "RNF-3000-24/8-0-SP"			
581913P003	NO			"9-1194609-2", "QS1500-NO.2-F6-0-65MM"			
5978892002	NO			"4-1194727-5", "DWP-125-1-1/2-0-STK"			
602909J001	NO			"2-1194772-1", "V4-5.0-0-SP-SM"			
603891J001	NO			"9-1194778-1", "V4-1.0-0-SP-SM"			
6519834003	NO			"1-1195147-1", "VERSAFIT-1/4-4-SP"			
678427-000	NO			"4-1195333-4", "VERSAFIT-1/2-3-SP"			
721053-000	NO			"6-1195638-4", "VERSAFIT-1/2-0-FSP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
7421224003	NO			"3-1199956-7", "RNF-3000-4.5/1.5-0-SP"			
744521J001	NO			"1-1195808-8", "V2-15.0-0-FSP-SM"			
7580142002	NO			"DWP-125-3/8-0-STK", "1448852-3"			
769283-000	NO			"4-1195994-9", "RNF-100-3/8-WH-FSP"			
771113P006	NO			"4-1196007-3", "FL2500-NO.2-I9-0-65MM"			
774185P009	NO			"8-1196028-7", "QS1500-NO.1-F5-0-STK"			
8014642003	NO			"2-1196196-6", "ATUM-16/4-0-STK"			
8839742003	NO			"7-1196879-0", "ATUM-4/1-0-STK", "ATUM-4/1-0-STK"			
902837J001	NO			"3-1197016-5", "V2-2.0-0-SP-SM"			
958133P007	NO			"1197417-6", "QS1500-NO.4-F8-0-STK"			
9585064004	NO			"1197420-6", "VERSAFIT-3/16-6-SP"			
CB0929-000	NO			"FL2500-NO.0-I7-0-STK"			
CB5018-000	NO						
CB5106-000	NO						
CB5107-000	NO			"HRHF-125FR-10/97", "3-1899833-5"			
CB5143-000	NO			"HRSR-125FR-10", "5-1899230-1"			
CB5150-000	NO			"HRSR-200FR-10", "3-1899225-2"			
CL0858-000	NO			"SST-48-03/FR/97"			
D20444-000	NO			"1-1199653-5", "FL2500-NO.1-I8-0-STK"			
D54859-000	NO			"1-1200678-9", "VERSAFIT-KIT-2-COLOR"			
E31091-000	NO			"1-1200722-2", "VERSAFIT-3/32-KT2-REFILL"			
NB07112001	NO			"BATTU-20.1/8.9-A1-0-STK", "8-1899840-1"			
NB09012001	NO						
NB09304001	NO						
NB09312001	NO			"ATUM--12/4-0-STK"			
NB11022001	NO						
NB11652001	NO			"ATUM--6/2-0-STK"			
NB11784001	NO						
NB12042001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
142003-000	NO			"1-1191029-3", "RNF-100-3/4-BK-FSP"			
1550634001	NO			"6-1191120-8", "VERSAFIT-3/8-0-FSP"			
1880984007	NO			"2-1191365-4", "RAYRIM-NR7-0-SP"			
2031134002	NO			"5-1191472-5", "VERSAFIT-3X-1/2-0-SP"			
2056350005	NO			"3-1191490-3", "ES-CAP-NO.3-B8-0-40MM"			
2056350007	NO			"3-1191490-4", "ES-CAP-NO.3-B8-0-50MM"			
3128592004	NO			"6-1192366-6", "CGAT-12/4-0-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
3813914003	NO			"2-1192851-4", "VERSAFIT-3/64-0-SP"			
415877P006	NO			"5-1193134-9", "FL2500-NO.1-I8-0-27MM"			
5020192003	NO			"9-1193753-3", "RP-4800-NO.6-0-STK"			
5020194004	NO			"9-1193753-5", "RP-4800-NO.6-0-SP"			
5038604008	NO			"1193794-5", "DCPT-6/3-45-SP"			
5052842057	NO			"3-1193821-9", "RNF-100-3/64-BK-STK"			
5052984151	NO			"6-1193831-9", "RNF-100-3/32-WH-SP"			
5053094268	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
5053292160	NO			"3-1193876-7", "RNF-100-1-BK-STK"			
5053302039	NO			"1193878-3", "RNF-100-1-RD-STK"			
5053394065	NO			"8-1193885-6", "RNF-100-2-BK-SP"			
5058714003	NO			"3-1193906-7", "VERSAFIT-1/8-9-SP"			
505872J005	NO			"7-1193906-2", "VERSAFIT-3/16-0-SP-SM"			
5500982001	NO			"3-1194338-9", "TAT-125-3/16-0-STK"			
5562734018	NO			"2-1194388-0", "VERSAFIT-1/16-0-SP"			
5677594005	NO			"2-1194496-8", "RNF-3000-12/4-0-SP"			
603891J001	NO			"9-1194778-1", "V4-1.0-0-SP-SM"			
721053-000	NO			"6-1195638-4", "VERSAFIT-1/2-0-FSP"			
7421224003	NO			"3-1199956-7", "RNF-3000-4.5/1.5-0-SP"			
7580142002	NO			"DWP-125-3/8-0-STK", "1448852-3"			
769283-000	NO			"4-1195994-9", "RNF-100-3/8-WH-FSP"			
771113P006	NO			"4-1196007-3", "FL2500-NO.2-I9-0-65MM"			
8014642003	NO			"2-1196196-6", "ATUM-16/4-0-STK"			
8839742003	NO			"7-1196879-0", "ATUM-4/1-0-STK", "ATUM-4/1-0-STK"			
902837J001	NO			"3-1197016-5", "V2-2.0-0-SP-SM"			
CB5018-000	NO						
D54859-000	NO			"1-1200678-9", "VERSAFIT-KIT-2-COLOR"			
E31091-000	NO			"1-1200722-2", "VERSAFIT-3/32-KT2-REFILL"			
NB09012001	NO						
NB09312001	NO			"ATUM--12/4-0-STK"			
NB11022001	NO						
NB11652001	NO			"ATUM--6/2-0-STK"			
NB12042001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
142003-000	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"1-1191029-3", "RNF-100-3/4-BK-FSP"			
1550634001	NO			"6-1191120-8", "VERSAFIT-3/8-0-FSP"			
1880984007	NO			"2-1191365-4", "RAYRIM-NR7-0-SP"			
2029154002	NO			"1-1191471-8", "RNF-150-1/2-0-SP"			
2031134002	NO			"5-1191472-5", "VERSAFIT-3X-1/2-0-SP"			
2056350005	NO			"3-1191490-3", "ES-CAP-NO.3-B8-0-40MM"			
2056350007	NO			"3-1191490-4", "ES-CAP-NO.3-B8-0-50MM"			
2376334004	NO			"1191747-3", "RNF-3000-9/3-8-SP"			
3128592004	NO			"6-1192366-6", "CGAT-12/4-0-STK"			
344153-000	NO			"1192592-8", "V4-3/16-0-SP"			
3813914003	NO			"2-1192851-4", "VERSAFIT-3/64-0-SP"			
4051444001	NO			"6-1193057-8", "VERSAFIT-1/4-2-SP"			
415877P006	NO			"5-1193134-9", "FL2500-NO.1-I8-0-27MM"			
5020192003	NO			"9-1193753-3", "RP-4800-NO.6-0-STK"			
5020194004	NO			"9-1193753-5", "RP-4800-NO.6-0-SP"			
5038114002	NO			"7-1193792-6", "DCPT-12/6-45-SP"			
5038184001	NO			"1-1193793-1", "DCPT-26/13-45-SP"			
5038604008	NO			"1193794-5", "DCPT-6/3-45-SP"			
5052842057	NO			"3-1193821-9", "RNF-100-3/64-BK-STK"			
5052984151	NO			"6-1193831-9", "RNF-100-3/32-WH-SP"			
5053094268	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
5053292160	NO			"3-1193876-7", "RNF-100-1-BK-STK"			
5053302039	NO			"1193878-3", "RNF-100-1-RD-STK"			
5053394065	NO			"8-1193885-6", "RNF-100-2-BK-SP"			
5058714003	NO			"3-1193906-7", "VERSAFIT-1/8-9-SP"			
505872J005	NO			"7-1193906-2", "VERSAFIT-3/16-0-SP-SM"			
5338834002	NO			"3-1194191-1", "VERSAFIT-3X-1/8-0-SP"			
5500982001	NO			"3-1194338-9", "TAT-125-3/16-0-STK"			
5509094059	NO			"6-1194348-3", "ATUM-6/2-0-SP"			
5509124055	NO			"1194353-1", "ATUM-40/13-0-SP"			
5562734018	NO			"2-1194388-0", "VERSAFIT-1/16-0-SP"			
5677594005	NO			"2-1194496-8", "RNF-3000-12/4-0-SP"			
5677604005	NO			"2-1194497-8", "RNF-3000-24/8-0-SP"			
602909J001	NO			"2-1194772-1", "V4-5.0-0-SP-SM"			
603891J001	NO			"9-1194778-1", "V4-1.0-0-SP-SM"			
678427-000	NO			"4-1195333-4", "VERSAFIT-1/2-3-SP"			
721053-000	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"6-1195638-4", "VERSAFIT-1/2-0-FSP"			
7421224003	NO			"3-1199956-7", "RNF-3000-4.5/1.5-0-SP"			
744521J001	NO			"1-1195808-8", "V2-15.0-0-FSP-SM"			
7580142002	NO			"DWP-125-3/8-0-STK", "1448852-3"			
769283-000	NO			"4-1195994-9", "RNF-100-3/8-WH-FSP"			
771113P006	NO			"4-1196007-3", "FL2500-NO.2-I9-0-65MM"			
8014642003	NO			"2-1196196-6", "ATUM-16/4-0-STK"			
8839742003	NO			"7-1196879-0", "ATUM-4/1-0-STK", "ATUM-4/1-0-STK"			
902837J001	NO			"3-1197016-5", "V2-2.0-0-SP-SM"			
9585064004	NO			"1197420-6", "VERSAFIT-3/16-6-SP"			
CB5018-000	NO						
CB5106-000	NO						
CB5107-000	NO			"HRHF-125FR-10/97", "3-1899833-5"			
CB5143-000	NO			"HRSR-125FR-10", "5-1899230-1"			
CB5150-000	NO			"HRSR-200FR-10", "3-1899225-2"			
CL0858-000	NO			"SST-48-03/FR/97"			
D54859-000	NO			"1-1200678-9", "VERSAFIT-KIT-2-COLOR"			
E31091-000	NO			"1-1200722-2", "VERSAFIT-3/32-KT2-REFILL"			
NB09012001	NO						
NB09312001	NO			"ATUM--12/4-0-STK"			
NB11022001	NO						
NB11652001	NO			"ATUM--6/2-0-STK"			
NB12042001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0021032009	NO			"9-1190015-4", "RBK-ILS-125-NR3-0-STK"			
0146662002	NO			"2-1198052-6", "DSPL-NR3-0-STK"			
142003-000	NO			"1-1191029-3", "RNF-100-3/4-BK-FSP"			
1550634001	NO			"6-1191120-8", "VERSAFIT-3/8-0-FSP"			
1880984007	NO			"2-1191365-4", "RAYRIM-NR7-0-SP"			
2029154002	NO			"1-1191471-8", "RNF-150-1/2-0-SP"			
2031134002	NO			"5-1191472-5", "VERSAFIT-3X-1/2-0-SP"			
2056350005	NO			"3-1191490-3", "ES-CAP-NO.3-B8-0-40MM"			
206247P038	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			
344153-000	NO			"1192592-8", "V4-3/16-0-SP"			
349871J001	NO			"2-1192632-5", "V4-7.0-0-SP-SM"			
3813914003	NO			"2-1192851-4", "VERSAFIT-3/64-0-SP"			
4051444001	NO			"6-1193057-8", "VERSAFIT-1/4-2-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5020194004	NO			"9-1193753-5", "RP-4800-NO.6-0-SP"			
5038114002	NO			"7-1193792-6", "DCPT-12/6-45-SP"			
5038604008	NO			"1193794-5", "DCPT-6/3-45-SP"			
5039582014	NO			"8-1193803-1", "TPEM-NR8-0-STK"			
5050964002	NO			"9-1193817-4", "RNF-100-NO.301-BK-SP"			
5052984035	NO			"6-1193831-8", "RNF-100-3/32-9-SP", "RNF-100-3/32-9-SP"			
5052984151	NO			"6-1193831-9", "RNF-100-3/32-WH-SP"			
5053034048	NO			"5-1193837-1", "RNF-100-1/8-9-SP"			
5053034137	NO			"5-1193837-2", "RNF-100-1/8-WH-SP"			
5053074017	NO			"2-1193843-7", "RNF-100-3/16-6-SP", "RNF-100-3/16-6-SP"			
5053094268	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
5053194052	NO			"2-1193862-7", "RNF-100-1/2-0-SP"			
5053204012	NO			"3-1193865-7", "RNF-100-1/2-2-SP"			
5053394065	NO			"8-1193885-6", "RNF-100-2-BK-SP"			
5058714003	NO			"3-1193906-7", "VERSAFIT-1/8-9-SP"			
5069794007	NO			"4-1193947-1", "CGPT-1.2/0.6-0-SP"			
5069864018	NO			"1193953-5", "CGPT-12.7/6.4-0-SP"			
5069964007	NO			"8-1193957-7", "CGPT-6.4/3.2-9-SP"			
5142422002	NO			"6-1198047-0", "DSPL-NR4-0-STK"			
5338834002	NO			"3-1194191-1", "VERSAFIT-3X-1/8-0-SP"			
5509094059	NO			"6-1194348-3", "ATUM-6/2-0-SP"			
5509124055	NO			"1194353-1", "ATUM-40/13-0-SP"			
5562734018	NO			"2-1194388-0", "VERSAFIT-1/16-0-SP"			
5575754001	NO			"9-1194397-4", "CGPT-18/6-0-SP"			
5677594005	NO			"2-1194496-8", "RNF-3000-12/4-0-SP"			
5677604005	NO			"2-1194497-8", "RNF-3000-24/8-0-SP"			
581913P003	NO			"9-1194609-2", "QS1500-NO.2-F6-0-65MM"			
5978892002	NO			"4-1194727-5", "DWP-125-1-1/2-0-STK"			
602909J001	NO			"2-1194772-1", "V4-5.0-0-SP-SM"			
603891J001	NO			"9-1194778-1", "V4-1.0-0-SP-SM"			
6519834003	NO			"1-1195147-1", "VERSAFIT-1/4-4-SP"			
678427-000	NO			"4-1195333-4", "VERSAFIT-1/2-3-SP"			
721053-000	NO			"6-1195638-4", "VERSAFIT-1/2-0-FSP"			
7421224003	NO			"3-1199956-7", "RNF-3000-4.5/1.5-0-SP"			
744521J001	NO			"1-1195808-8", "V2-15.0-0-FSP-SM"			
769283-000	NO			"4-1195994-9", "RNF-100-3/8-WH-FSP"			
774185P009	NO			"8-1196028-7", "QS1500-NO.1-F5-0-STK"			
958133P007	NO			"1197417-6", "QS1500-NO.4-F8-0-STK"			
9585064004	NO			"1197420-6", "VERSAFIT-3/16-6-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
CB0929-000	NO			"FL2500-NO.0-17-0-STK"			
CB5018-000	NO						
CB5106-000	NO						
CB5107-000	NO			"HRHF-125FR-10/97", "3-1899833-5"			
CB5143-000	NO			"HRSR-125FR-10", "5-1899230-1"			
CB5150-000	NO			"HRSR-200FR-10", "3-1899225-2"			
CL0858-000	NO			"SST-48-03/FR/97"			
D20444-000	NO			"1-1199653-5", "FL2500-NO.1-18-0-STK"			
NB09304001	NO						
NB11784001	NO						

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1880984007	NO			"2-1191365-4", "RAYRIM-NR7-0-SP"			
2029154002	NO			"1-1191471-8", "RNF-150-1/2-0-SP"			
2031134002	NO			"5-1191472-5", "VERSAFIT-3X-1/2-0-SP"			
2376334004	NO			"1191747-3", "RNF-3000-9/3-8-SP"			
344153-000	NO			"1192592-8", "V4-3/16-0-SP"			
4051444001	NO			"6-1193057-8", "VERSAFIT-1/4-2-SP"			
5020194004	NO			"9-1193753-5", "RP-4800-NO.6-0-SP"			
5038114002	NO			"7-1193792-6", "DCPT-12/6-45-SP"			
5038184001	NO			"1-1193793-1", "DCPT-26/13-45-SP"			
5052984151	NO			"6-1193831-9", "RNF-100-3/32-WH-SP"			
5338834002	NO			"3-1194191-1", "VERSAFIT-3X-1/8-0-SP"			
5509094059	NO			"6-1194348-3", "ATUM-6/2-0-SP"			
5509124055	NO			"1194353-1", "ATUM-40/13-0-SP"			
5677594005	NO			"2-1194496-8", "RNF-3000-12/4-0-SP"			
5677604005	NO			"2-1194497-8", "RNF-3000-24/8-0-SP"			
602909J001	NO			"2-1194772-1", "V4-5.0-0-SP-SM"			
603891J001	NO			"9-1194778-1", "V4-1.0-0-SP-SM"			
678427-000	NO			"4-1195333-4", "VERSAFIT-1/2-3-SP"			
7421224003	NO			"3-1199956-7", "RNF-3000-4.5/1.5-0-SP"			
744521J001	NO			"1-1195808-8", "V2-15.0-0-FSP-SM"			
769283-000	NO			"4-1195994-9", "RNF-100-3/8-WH-FSP"			
9585064004	NO			"1197420-6", "VERSAFIT-3/16-6-SP"			
CB5018-000	NO						
CB5106-000	NO						
CB5107-000	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"HRHF-125FR-10/97", "3-1899833-5"			
CB5143-000	NO			"HRSR-125FR-10", "5-1899230-1"			
CB5150-000	NO			"HRSR-200FR-10", "3-1899225-2"			
CL0858-000	NO			"SST-48-03/FR/97"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
0021032009	NO			"9-1190015-4", "RBK-ILS-125-NR3-0-STK"			
0146662002	NO			"2-1198052-6", "DSPL-NR3-0-STK"			
142003-000	NO			"1-1191029-3", "RNF-100-3/4-BK-FSP"			
1550634001	NO			"6-1191120-8", "VERSAFIT-3/8-0-FSP"			
1880984007	NO			"2-1191365-4", "RAYRIM-NR7-0-SP"			
2029154002	NO			"1-1191471-8", "RNF-150-1/2-0-SP"			
2031134002	NO			"5-1191472-5", "VERSAFIT-3X-1/2-0-SP"			
2056350005	NO			"3-1191490-3", "ES-CAP-NO.3-B8-0-40MM"			
206247P038	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			
344153-000	NO			"1192592-8", "V4-3/16-0-SP"			
349871J001	NO			"2-1192632-5", "V4-7.0-0-SP-SM"			
3813914003	NO			"2-1192851-4", "VERSAFIT-3/64-0-SP"			
4051444001	NO			"6-1193057-8", "VERSAFIT-1/4-2-SP"			
5020194004	NO			"9-1193753-5", "RP-4800-NO.6-0-SP"			
5038114002	NO			"7-1193792-6", "DCPT-12/6-45-SP"			
5038184001	NO			"1-1193793-1", "DCPT-26/13-45-SP"			
5038604008	NO			"1193794-5", "DCPT-6/3-45-SP"			
5039582014	NO			"8-1193803-1", "TPEM-NR8-0-STK"			
5050964002	NO			"9-1193817-4", "RNF-100-NO.301-BK-SP"			
5052984035	NO			"6-1193831-8", "RNF-100-3/32-9-SP", "RNF-100-3/32-9-SP"			
5052984151	NO			"6-1193831-9", "RNF-100-3/32-WH-SP"			
5053034048	NO			"5-1193837-1", "RNF-100-1/8-9-SP"			
5053034137	NO			"5-1193837-2", "RNF-100-1/8-WH-SP"			
5053074017	NO			"2-1193843-7", "RNF-100-3/16-6-SP", "RNF-100-3/16-6-SP"			
5053094268	NO			"4-1193845-5", "RNF-100-1/4-BK-SP"			
5053194052	NO			"2-1193862-7", "RNF-100-1/2-0-SP"			
5053204012	NO			"3-1193865-7", "RNF-100-1/2-2-SP"			
5053394065	NO			"8-1193885-6", "RNF-100-2-BK-SP"			
5058714003	NO			"3-1193906-7", "VERSAFIT-1/8-9-SP"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
5069794007	NO			"4-1193947-1", "CGPT-1.2/0.6-0-SP"			
5069864018	NO			"1193953-5", "CGPT-12.7/6.4-0-SP"			
5069964007	NO			"8-1193957-7", "CGPT-6.4/3.2-9-SP"			
5142422002	NO			"6-1198047-0", "DSPL-NR4-0-STK"			
5338834002	NO			"3-1194191-1", "VERSAFIT-3X-1/8-0-SP"			
5509094059	NO			"6-1194348-3", "ATUM-6/2-0-SP"			
5509124055	NO			"1194353-1", "ATUM-40/13-0-SP"			
5562734018	NO			"2-1194388-0", "VERSAFIT-1/16-0-SP"			
5575754001	NO			"9-1194397-4", "CGPT-18/6-0-SP"			
5677594005	NO			"2-1194496-8", "RNF-3000-12/4-0-SP"			
5677604005	NO			"2-1194497-8", "RNF-3000-24/8-0-SP"			
581913P003	NO			"9-1194609-2", "QS1500-NO.2-F6-0-65MM"			
5978892002	NO			"4-1194727-5", "DWP-125-1-1/2-0-STK"			
602909J001	NO			"2-1194772-1", "V4-5.0-0-SP-SM"			
603891J001	NO			"9-1194778-1", "V4-1.0-0-SP-SM"			
6519834003	NO			"1-1195147-1", "VERSAFIT-1/4-4-SP"			
678427-000	NO			"4-1195333-4", "VERSAFIT-1/2-3-SP"			
721053-000	NO			"6-1195638-4", "VERSAFIT-1/2-0-FSP"			
7421224003	NO			"3-1199956-7", "RNF-3000-4.5/1.5-0-SP"			
744521J001	NO			"1-1195808-8", "V2-15.0-0-FSP-SM"			
769283-000	NO			"4-1195994-9", "RNF-100-3/8-WH-FSP"			
774185P009	NO			"8-1196028-7", "QS1500-NO.1-F5-0-STK"			
958133P007	NO			"1197417-6", "QS1500-NO.4-F8-0-STK"			
9585064004	NO			"1197420-6", "VERSAFIT-3/16-6-SP"			
CB0929-000	NO			"FL2500-NO.0-I7-0-STK"			
CB5018-000	NO						
CB5106-000	NO						
CB5107-000	NO			"HRHF-125FR-10/97", "3-1899833-5"			
CB5143-000	NO			"HRSR-125FR-10", "5-1899230-1"			
CB5150-000	NO			"HRSR-200FR-10", "3-1899225-2"			
CL0858-000	NO			"SST-48-03/FR/97"			
D20444-000	NO			"1-1199653-5", "FL2500-NO.1-I8-0-STK"			
NB07112001	NO			"BATTU-20.1/8.9-A1-0-STK", "8-1899840-1"			
NB09304001	NO						
NB11784001	NO						