



CUSTOMER OPERATIONS
160 RIO ROBLES
SAN JOSE, CA 95134

PDN #: M000814

DATE: 13-Nov-2015

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	806-0727-20+T	N/A			Part reactivated from prior notice: M000793
Reactivation	MAX9503MEEE+	N/A			Part reactivated from prior notice: M000805
Reactivation	MAX9503MEEE+T	N/A			Part reactivated from prior notice: M000805
Reactivation	MAX9503METE+	N/A			Part reactivated from prior notice: M000805
Reactivation	MAX9503METE+T	N/A			Part reactivated from prior notice: M000858I
Lead-Free Conversion	ICL7611DCPA-2	N/A	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX116EAX	MAX116EAX+	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX150BEWP-TG074	N/A	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX1833EUT	MAX1833EUT+	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX1945REUI/GH9	MAX1945REUI+	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX232EWE/R70350	N/A	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX291EWE-G095	N/A	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX292EWE-G90095	N/A	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX295CWE-G095	N/A	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX296CWE-G095	N/A	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX5200ACUB	N/A	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX5201ACUB	N/A	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX5202BEUB	N/A	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX5204ACUB	N/A	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX5205AEUB	N/A	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX5250BEAP-TG071	N/A	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX5584EUP	N/A	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX6043CAUT33	MAX6043CAUT33+	13-May-2016	12-Nov-2017	Leaded with a Lead-Free or RoHS Replacement
Lead-Free Conversion	MAX683EUA-TG069	N/A	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX713CSE	MAX713CSE+	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX713EPE	MAX713EPE+	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 14-Dec-2015

Lead-Free Conversion	MAX8875EUK33/GH9	MAX8875EUK33+	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	MAX8875EUK33/GH9-T	MAX8875EUK33+	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	REF02CSA.TG107	N/A	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Lead-Free Conversion	REF02EP-G107	N/A	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Discontinuance	AD674AKN	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	DS1679B	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	DS2432P-W07+3	N/A	15-May-2016	12-Nov-2017	The part was not released
Discontinuance	ICL7106BCPL-4	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	ICL7116BCPL-4	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	ICL7621AESA	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	ICL7664ACSA	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	ICL7664CSA	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX13081ECPA	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX1474AXT+	N/A	15-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX1474AXT+T	N/A	15-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX1644BEAE	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX1651CPA	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX1686ESA	N/A	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Discontinuance	MAX252ACHL-W	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX252AEHL-W	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX3212CWI	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX3225EPP	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX32580-LNJ+	MAX32590-LNJ+	13-Nov-2015	13-Nov-2015	The part was not released
Discontinuance	MAX32590-KIT#	MAX32590-EVK#	13-Nov-2015	13-Nov-2015	EVKIT is No Longer Supported
Discontinuance	MAX3325CAI	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX3385ECAP	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX36025+	DS3640B+	15-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX36025+T	DS3640B+TRL	13-Nov-2015	13-Nov-2015	The part was not released
Discontinuance	MAX36025EVKIT#	DS3640K	13-Nov-2015	13-Nov-2015	EVKIT is No Longer Supported
Discontinuance	MAX4133ESD	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX4142ESD/GH9	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX4243ESD	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX4327ESD	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX4432ESA	N/A	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Discontinuance	MAX5290AEUD	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX561CWI	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured

Discontinuance	MAX652CPA	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX7233AFIPL	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX736EPD	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX775CPA	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX797CPE	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX860CPA	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX870EPA	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX873BCSA-TG068	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX882EPA	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MAX9380EUA	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MX7535KEWI	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MX7541JP	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MX7541KP	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MX7545GLP	N/A	13-May-2016	12-Nov-2017	Part can no longer be manufactured
Discontinuance	MX7828LEAI	N/A	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Discontinuance	MX7845BEWG	N/A	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Discontinuance	MX7845BEWG/GH9	N/A	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version
Discontinuance	MXL1116CS8	N/A	13-May-2016	12-Nov-2017	Part is leaded. Request information on lead-free version