



AKM Semiconductor, Inc.

End of Life Notice

Document ID : AKMSPK151016A
 Product affected : Listed below
 Date of notification : 10/16/2015
 Type of change : N/A
 Reason for change : Vendor's decision
 Last order date : Mar.30, 2016
 Last shipment date : Sep.30, 2016

Description :

AKM will discontinue below listed products due to closure of assembly house.

Product affected :

AK4115VQ	AK4399EQ	AK4685EQ	AK8434VQ
AK4392EQ	AK4586VQ	AK5366VQ	AK8440VQ
AK4397EQ	AK4683EQ	AK7601VQ	

Suggested replacement product

Affected product	Suggested replacement product (functional equivalent product)	
AK4115VQ	AK4118AEQ	http://www.akm.com/akm/en/file/datasheet/AK4118AEQ.pdf
AK4392EQ	AK4490EQ	http://www.akm.com/akm/en/file/datasheet/AK4490EQ.pdf
AK4397EQ	AK4490EQ	http://www.akm.com/akm/en/file/datasheet/AK4490EQ.pdf
AK4399EQ	AK4490EQ	http://www.akm.com/akm/en/file/datasheet/AK4490EQ.pdf
AK4586VQ	AK4626AVQ AK4113VF *Equivalent to 2 parts combined	http://www.akm.com/akm/en/file/datasheet/AK4626AVQ.pdf http://www.akm.com/akm/en/file/datasheet/AK4113VF.pdf
AK4683EQ	AK4118AEQ AK4454VT AK5552VT *Equivalent to all 3parts combined	http://www.akm.com/akm/en/file/datasheet/AK4118AEQ.pdf http://www.akm.com/akm/en/file/datasheet/AK4454VT.pdf http://www.akm.com/akm/en/file/datasheet/AK5552VT.pdf
AK4685EQ	AK4695EQ	Please contact AKM for datasheet
AK5366VQ	AK5365VQ	http://www.akm.com/akm/en/file/datasheet/AK5365VQ.pdf
AK7601VQ	AK7601AVQ	http://www.akm.com/akm/en/file/datasheet/AK7601AVQ.pdf
AK8434VQ	AK8432VQ	Please contact AKM for datasheet
AK8440VQ	None	

AKM will consider this notice fully noticed and approved unless specific conditions of acceptance are provided in writing within 30 days of receipt of this notice.

Ryo Inoue
Sales Administration Manager
AKM Semiconductor, Inc.
1731 Technology Drive, Suite 500
San Jose, CA 95110