

TDK Distributors**TDK Corporation**

MAGNETICS BG

GM

Teppei Watanabe

Process Change Notice

■MHQ0402 series addition of production location■

Approval request for manufacturing location addition:

Current: Japan/TDK Akita Corporation

Addition: China/TDK Dalian Corporation

This addition does not cause any additional changes regarding manufacturing method and manufacturing control.

Address of current factory: Aza-haraikawa, Sankawa, Ouchi, yurihonjo-shi, Akita-ken 018-0731 Japan

Address of added factory: 68 West Huaihe Rd., Dalian Economic and Technical Development Zone Dalian, P.R.China

Current	After change
< Location > Japan/TDK Akita Corporation	< Location > Japan/TDK Akita Corporation China/TDK Dalian Corporation

Your part number: Please refer to Applicable part number list.

Our part number: Ceramic inductors (For details, please see attached part number list.)

Process flow: Please refer to Process flow.

HS Code: Products HS code 8504.50-000.

These applicable products are currently manufactured at TDK Akita Corporation.

In order to maintain a stable supply associated with capacity increase and to avoid disaster risk by dispersed location, TDK Dalian Corporation is required to be approved.

Already in the TDK Dalian we have started mass production of MLG1005, MLG0603 and MLG0402 series.

This change does not cause any additional changes regarding our part name or part number you use.

If this "information for change" will not be returned to us by scheduled date of implementation,

we will consider it is approved and then will deliver the products manufactured by TDK Akita Corporation

or TDK Dalian Corporation from Jul, 2018 onward, without any further notice.

Planned Date: 2018/Jul

Response Date By: 2018/Apr/27

Last Order date for current spec:Not Applicable

Attachment : No

ANSWER SHEET

To TDK Corporation MAGNETICS BG	Company Department Name
Approval Date: _____	Directions

