
Notice of Discontinuation for TAIYO YUDEN (U.S.A.) Inc. Distributors

DATE: December 14th, 2018
RE: Discontinuation of Wire-wound Chip Power Inductors (BRL2515 series)
REF NO.: UTY-DN18-05D

TAIYO YUDEN (U.S.A.) Inc. hereby gives notice that the following part numbers are to be discontinued effective 90 days from the issue of this notice for all TAIYO YUDEN (U.S.A.) Inc. distributors. Please note that any last time buys must be made within the aforementioned 90 day discontinuation window, meaning an effective LTB date of **3/14/2019**. Orders for these components received after the issue date of this notice are Non-Cancelable and Non-Returnable.

Discontinued Part Numbers	Suggested Alternative Part Numbers
BRL2515T1R0M	BRL2518T1R0M
BRL2515T1R5M	BRL2518T1R5M
BRL2515T2R2M	BRL2518T2R2M
BRL2515T3R3MD	BRL2518T3R3M
BRL2515T4R7MD	BRL2518T4R7M

***Please note the suggested alternative part numbers are not direct, drop-in replacements. Therefore, the part number spec/datasheet should be consulted for comparison details.**

NOTE: The information in this notice is applicable only to TAIYO YUDEN (U.S.A.) Inc. distribution sales channels. Discontinuation and promotional status changes, change schedules, and availability may vary in other regions. Please contact the Taiyo Yuden sales office responsible for sales in your country for details on this notice.

Issued by TAIYO YUDEN (U.S.A.) INC.
Sales Planning Department